






Martin County, FL




Project Location

- Golden Gate CRA is located in Martin County,
 Florida
- Total area: Approximately 380 acres
- Boundaries:
 - West: Highway A1A
 - East: Tributary of the St. Lucie River
 - North: Witham Field
 - South: Stuart Yacht & Country Club subdivision
- Entire neighborhood falls within Golden Gate CRA boundaries
- Includes residential streets, parks, transit stops, and community facilities





Project Schedule








Demographics & Land Use

Population: ~5,070

 Poverty rate: 20.1% (higher than county average)

- Housing mix: 44.6% single-family,
 44.1% duplex
- Zoning: Mainly residential with commercial along Dixie Hwy






Project Site Visit












Roadway Infrastructure

- Arterial: Dixie Hwy (19,200 AADT)
- Collectors: Indian St (6,200 AADT),
 Jefferson St (900 AADT)
- Local roads: Mostly 50' ROW, limited traffic calming
- Intersection needs: Dixie & Indian
 St key junction





5 Year Crash Statistics

- 1083 total crashes (1/2015-12/2024)
- 8% off-road, 12% sideswipe, 19% rear-end
- 16 Pedestrian Crashes, 68% of Ped Crashes happened at Night
- 44% of crashes due to lane deviation, failure to yield, or tailgating
- Pedestrian signage and lighting gaps noted

1083 Total Crashes



259 Injury (24% of Total Crashes)

Rear End (19% of Total Crashes)

129 Sideswipe

(12% of Total Crashes) 85
Off Road
(8% of Total Crashes)

Top 3 Violations



DUI (9%)



95
Distracted
Driving
(9%)



288
Failure to
Keep Lane
(26%)



Pedestrian

Crashes

• 1 - Fatality

 68% of Ped Crashes happened at Night



75% of crashes happen during the daytime, however 50% of all Fatal Crashes occurred at night



Multimodal Access

- 36,610 ft of sidewalks, mostly disconnected
- Sidewalks on both sides: Dixie
 Hwy, parts of Evergreen
- No dedicated bike lanes or shareduse markings
- El Camino Trail under development






Transit Conditions

- MARTY Route 3: 2 stops
 (Evergreen & Cassidy Center)
- Shelters and seating only located at Cassidy Center Stop
- Poor pedestrian access due to sidewalk gaps
- Riders must walk in roadways to reach transit










Parking Demand


- High on-street parking usage observed near residential clusters
- Driveway and off-street parking limited for duplex and multi-unit housing
- Informal parking often occurs in unpaved yards or swale areas
- No marked or regulated parking zones, leading to inconsistent use





Drainage Infrastructure

- Open swale drainage system with overgrown and encroached trenches
- Flooding limits mobility after storms
- Recent land acquired for retention, but CRA plan lacks full drainage upgrade
- Underground drainage needed to support new curbs/sidewalks





Public Spaces & Lighting

- Cassidy Center: park, playground, sports courts, transit access
- Lighting gaps: only Evergreen,
 Jefferson, and Dixie well lit
- Tree canopy: 18.15% (below USDA 30% goal)





Existing vs. Planned Improvements

- CRA Plan covers sidewalk buildout and some lighting upgrades
- Major gaps: drainage upgrades, full lighting, transit stop amenities
- Existing conditions often conflict with new sidewalk placement

