
## DEPT-5




1


### **OUTLINE**

- Flood Statistics
- Review of Impacted areas
- Recognition of staff






Л




# FLOODED HOMES – UNINCORPORATED MC





32 Confirmed - 9 with Major Damage per DEM review
















### HOBE SOUND SANDCASTLE CIRCLE



#### **Pump Statistics**

- 6" Pump for 10+ days
- ¼ mile of lay flat discharge line
- Tied into existing swale system to the south

